MT631-NL

CROSS HANDLE STRAIGHT SWEAT VALVE


SPECIFICATION SHEET


- -1/2" COPPER SWEAT INLET
- -3/8" O.D. COMPRESSION OUTLET
- -5" SWEAT EXTENSION (CAN BE CUT TO SIZE)
- -BRASS CROSS HANDLE WITH 1/4 TURN BALL VALVE
- -OFFERED IN MANY FINISHES
- -OTHER FINISHES AVAILABLE UPON REQUEST
- -LEAD FREE IN COMPLIANCE WITH NSF 372














WARRANTY

FOR WARRANTY INFO PLEASE VISIT WWW.MOUNTAINPLUMBING.COM/PAGE/RESOURCES/WARRANTY

FINISH CARE & MAINTENANCE

NEVER USE ANY HARSH ALKALI, ACID BASED DETERGENTS OR CLEANERS SUCH AS SOFT SCRUB®, SCRUBBING BUBBLES® OR COMET® TO CLEAN. DO NOT USE BRILLO® OR SCOTCH BRITE® PADS. THESE WILL ALL HARM THE FINISH. TO CLEAN, USE ONLY A DAMP SOFT CLOTH AND WIPE GENTLY. STANDARD WINDEX® CAN ALSO BE USED SPARINGLY. IT IS NOT NECESSARY TO WIPE HARD TO REMOVE SPOTS. TO MAINTAIN THE FINISH, WIPE WITH A SOFT DRY CLOTH AFTER USE. AN OCCASIONAL COAT OF PURE CARNAUBA WAX WITHOUT CLEANERS WILL HELP PORTECT THE FINISH.